## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

According to a plat filed at the Baker County Surveyors Office on June 29, 1994, survey number 10-37-37. Surveyed by Hanley Engineering for Evan Hale on April 2- June 15, 1994.

Set 5/8" x 30" rebar and plastic cap marked " HANLEY ENGRG PLS 1206"

DIAGRAM		
1 NE S 8 16	,	
RLS 1060 1995		

Description of corner evidence found:

Found a 5/8" x 30" rebar with a yellow plastic cap, marked "HANLEY ENGR. PLS 1206".

Description of monument and accessories I established to perpetuate the original location of this corner:

At rebar position, set a USFS 31/4" aluminum capped monument 18" in the ground, with a mound of stone to cap, rebar set inside the pipe, from which:

A pine, 9" in diam., bears N.31°30'E., 26.4 ft., double blazed and scribed "NE1/16S8BT" with nail and brass washer "RLS 1060", on face of blaze. A pine, 7" in diam., bears S.12°30'E., 22.2 ft., double blazed and scribed "NE1/16S8BT" with nail and brass washer "RLS 1060", on face of blaze.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

R. Cherf Solvering 7-15-96

OREGON
JUNE 18, 1976
R. DAVID SCHURIAN
1060

Office of State of for record on the da	County of	within instrument was filed in this office
(COUNTY OF)	FICIAL)	(DEPUTY)

F-8

FILED 7-15-96

BAKER COUNTY SURVEYOR

SURVEY NO. 10-37-83