
# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

TOWNSHIP IO SOUTH, RANGE 44 EAST

Southeast corner section 18, T. 10 S., R. 44 E. of the W.M.

#### History of original corner

Original corner set by W.B. Barr
Deputy Surveyor under contract
Number 388, dated May 7, 1881.
Set marked basalt rock 14" x 12"
x 9" raised Mound of stone per instructions.



#### Subsequent survey:

None.

## Description of evidence found:

None

## Description of monument and accessories

established to perpetuate the location of this corner:

At double proportionate distance I set a 5/8" diameter x 30" long iron rod and 2" Diameter aluminum cap marked:

From the corner point:

A 5/8" diameter x 30" long iron rod with a 1.3" diameter yellow plastic cap marked "LS1015" bears North 30° West 7.13 feet.

A 5/8" diameter x 30" long iron rod with a 1.3" diameter yellow plastic cap marked "LS1015" bears North 42° East 16.19 feet.

A 5/8" diameter x 30" long iron rod with a 1.3" diameter yellow plastic cap marked "LS1015" bears South 40° East 6.86 feet.

A 5/8" diameter x 30" long iron rod with a 1.3" diameter yellow plastic cap marked "LS1015" bears South 70° West 9.54 feet.

Compass declination 19° East.

Corner position falls in a clump of large boulders.

I hereby certify that the above corner point was perpetuated as herein described on 11/16/01.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1974
RICHARD A. SHAVER

Timberline Surveys
P.O. Box 61
Wallowa, Oregon 97885

Phone 541-886-2605 Registration expires 6/30/02

FILED JONE 3, 2002

BAKER COUNTY SURVEYOR

SURVEY NO. 10-44-9

CP#89