CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established this survey.

DIAGRAM							
	T	11	s	R	37	E	
	V	N -	<u>1</u>	2	20		
			7 s.			:	
				. •			

Description of corner evidence found:

Description of manument and accessories I established to perpetuate the original location of this corner.

Set a $2\frac{1}{2}$ inch brass cap on a 2 inch iron pipe 31 inches long, 27 inches in the ground and a 6 foot steel fence post alongside with signs 54-9 and 54-2 attached, from which

New bearing trees:

A pine, 9 ins diam bears N 64° W, 74.3 ft dist marked 1/16 S 20 BT A pine, 8 ins diam bears N 33° W, 88.5 ft dist marked 1/16 S 20 BT

Each BT has a sign 54-3 attached 6 inches below a band of red paint and has a brass washer marked LS 1206 nailed flush with BT blaze.

Brass cap is marked thus:

T 11 S R 37 E

 $W = \frac{1}{16} = \frac{5 \cdot 20}{5 \cdot 29}$

1978 ORLS 1206

REGISTERED PROFESSIONAL LAND SURVEYOR

enus #

OREGON SEPTEMBER 23, 1977 JAMES D. HANLEY 1206 I hereby certify the above corner monument was correctly established on June 16, 1978 witnesses by T. Hanley, R. McKim, and T. Fisk.

Office of County Surveyor	County of. Baker	
State of Oregon	t the within instrument was filed	in this office
for record on the day of	, 19	
(COUNTY OFFICIAL)	(I)EPLITY)	

Fran R6-7100-57 (9/71)

MID 6-30-78

MER COUNTY SURVEYOR

CHRYFY NO. 11-37-18

12 GPO -798-276