CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established this survey.

DI	AGRAM	
Т	11 S	R 37 E
S	S 1/	'16 S 20

Description of corner evidence found:

Description of monument and accessories l'established to perpetuate the original location of this corner.


Set a $2\frac{1}{2}$ inch brass cap on a 2 inch iron pipe, 31 inches long, 26 inches in the ground with a steel fence post alongside with signs 54-2 and 54-9 attached from which:

A pine, 6 ins. diam. bears S. 22° W., 16.0 ft. dist. marked 1/16 S 19 BT A pine, 9 ins. diam. bears S. 54° W., 31.5 ft. dist. marked 1/16 S 19 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1206 nailed flush with BT blaze.

Brass cap marked thus:

T 11 S R 37 E



	S I	1/16		
s	19		S	20
	19	78		
	ORLS	1206	•	

I hereby certify the above corner was established on June 16, 1978, witnessed by T. Hanley, R. McKim and T. Fisk.

Office of. County Surveyor	Baker
State of Oregon I hereby certify	that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	у(ДЕРИТУ)

Form R6-7100-57 (9/71)

TABLE COUNTY SURVEYOR

Y NO. 11-37-23

対 GPO -798-276