

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Herman D. Gradon, Under General
Land Office Contract No. 416. Surveyor Generals Notes State:
Set a sandstone 14x10x5 ins. 9" in the ground for $\frac{1}{4}$ section corner
marked $\frac{1}{4}$ on N face. From which:
A Pine 24" dia. bears North 154 lks dist., marked $\frac{1}{4}$ S BT.
A Pine 24" dia. bears S25°E, 107 lks dist., marked $\frac{1}{4}$ S BT.

CONTINUED ON ATTACHED SHEET.

DIAGRAM

T11S R37E
 $\frac{1}{4}$ S16W face.
S21
1974
B.L.M.

Description of corner evidence found:


Found brass cap monument as established by B.L.M. in 1974, in good condition.
Found bearing trees as established and described by the B.L.M. in 1974, in good condition.

Description of monument and accessories established to perpetuate the original location of this corner:

Maintained corner by setting posts with warning and boundry sign East and West 5 ft.
from corner.
Painted 6" red band around trees and nailed bearing tree signs to trees.

Corner monumented 9-7-83

Witnessed by D. Mitchell Ferguson



Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

by (DEPUTY)

Form R6-7100-57 (9/71)

FILED Nov. 17, 1983
BAKER COUNTY SURVEYOR
SURVEY NO. 11-37-49

GPO—798-278