## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner originally established by Eugene P. McCornack under Contract No. 398 and dated July 02, 1881.

Surveyor General records state:

Set basalt stone 12 x 11 x 9", 8" in ground for 1/4 Sec Cor marked 1/4 on N face and raised a mound of stone alongside, pits impracticable.

DIAGRAM
T 11 S R 37 E

\[ \frac{1}{4} & \frac{\text{S} 32}{\text{S} 5} \]

T 12 S

1987

PLS 1106

## Description of corner evidence found:

None. Corner searched 4 sepærate times with 2 person crew including 1 PLS. Believe corner is destroyed by road. USFS search by J. Mitchell was for N1/4 Sec 32, not this corner. Total search time was 6 hours.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Re-established corner by single proportionate measure between found N1/4S6 and found NE corner of sec 5... NOTE: There is an old location poster saying "Approx  $\frac{1}{4}$ "SE of corner point about 30' on a fence.

Set  $2\frac{1}{2}$ " aluminum pipe with  $2\frac{1}{2}$ " aluminum cap 22" in the ground and surrounded with a mound of earth and stone. Cap marked as shown in corner diagram.

New bearing tree established: A 10" juniper brs N07 $\frac{1}{2}$  W, 75.7' dist mkd 1/4S32 BT on double blaze. No BT is available in Sec 5 so a reference monument was set. Reference monument is a 5/8" x 30" rebar with  $1\frac{1}{2}$ " aluminum cap mkd as shown. Set steel fence post next to reference monument and attached sign 54-3 & 54-9. The reference monument brs S64 $\frac{1}{2}$  E, 17.7' from corner.

New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Attached signs 54-3 & 54-9, painted face of blaze and 6" band of red around each BT. Set steel fence post East of corner and attached sign 54-9.

Compass declination  $19^{O}$  East.

I hereby certify that the above corner monument was properly re-established to U.S.F.S. standards by me on November 03, 1987.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Wille R. Wells

Office of County Surveyor County of Baker	
State ofOregon I hereby certify that the within instrument was filed in this office	
for record on the day of , 19	
by	
(COUNTY OFFICIAL) (DEPUTY)	

Form R6-7100-57 (9/71)

☆ GPO---798-276

1-21-88

LARER COURTY EARVEYOR

SURVEY NO. 11-37-71