History of original corner establishment:

N/A

DIAGRAM

T11S R37E N 1/16 S27 | S26

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

T11S R37E N 1/16 S27/S26 1995 LS 896

Set: $2\frac{1}{2}$ "x30" alum. pipe with a $2\frac{1}{2}$ " alum. cap 24" in ground to bedrock. No stone available. Stamped:

Marked:

13" Ponderosa Pine $N19\frac{1}{2}W$ --22.7' Scribed N 1/16 S27 BT.

11" D-Fir N84½E--14.2' Scribed N 1/16 S26 BT.

Nailed 54-9 and 54-3 signs to BT's, painted bands and blazes red and nailed a 1" brass disk stamped PLS 896 flush between the B and T. Set guard post West with 54-2 and 54-9 signs.

Bearings are true by instrument tie.

REGISTERED
PROFESCIONAL
LAND SURVEYOR

July D. Aurany

OREGON
LARRY D. BISHOP

838

Expires 12/1/195

Office of	County of	
State of, / hereb	y certify that the within instrument was filed in thi	s office
for record on the day of	, 19	
	by	
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

FILED FEB. 4, 1998
BAKER COUNTY SURVEYOR
SURVEY NO. 11-37-108

*GPO-591-971, 1988