History of original corner establishment:

N/A

DIAGRAM

T11S R37E SE 1/16 S35

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

T11S R37E SE 1/16 S35 1995 LS 896

Set: $2\frac{1}{2}$ "x30" alum. pipe with a 3" alum. cap 10" in ground in a mound of stone and earth $4\frac{1}{2}$ ' base to top. Stamped:

12" Ponderosa Pine N47 $\frac{1}{4}$ W--9.4' Scribed SE 1/16 S35 BT.

12" Ponderosa Pine N74½E--17.4' Scribed XBT. Nailed 54-9 and 54-3 signs to BT's, painted bands and blazes red and nailed a 1" brass disk stamped PLS 896 flush between the B and T. Set guard post West with 54-2 and 54-9 signs.

Bearings are true by instrument tie.

REGISTERED PROFESSIONAL LAND SURVEYOR y V. Busing OREGON LARRY D. BISHOP EX/120 12/31195

Office of	County of
State of, / hereby certify that the within instrument was filed in this office	
for record on the day of	, 19
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

*GPO-591-971, 1988

FLED FEB. 4, 1998 BAKER COUNTY SURVEYOR SURVEY NO. 11-37-140