

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 0-2

History of original corner establishment:
Baker County Survey Records show no previous establishment of this corner.

DIAGRAM
T11S R41E
NW1/16
S19
1989
PLS 848

Description of corner evidence found:

Baker County Survey Records show no previous establishment of this corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, Set 26" in the ground.

From Which:

Set 1/2"x24" iron pins with aluminum caps, as follows:

N20 01'E., 11.0 ft., stamped NW 1/16 S19, RM and an arrow with course to the corner and 1989, PLS 848.

S86 11'W., 91.40 ft., stamped NW 1/16 S19, RM and an arrow with course to the corner and 1989, PLS 848. This Pin is part of the survey control network. Set a steel post with warning sign alongside this pin.

Measurements to pins taken with electronic tachimeter with angles turned from the survey control network. Set steel fence posts with Warning and Boundary signs 4 ft. South & West from the monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1953
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
D. Mitchell Ferguson & Ken H. Delano
On Nov. 30, 1989
Refer to Baker Co. Survey No. 11-41-6 - 1

Office of _____ County of _____
State of _____ I hereby certify that the within instrument was filed
in this office for record on the _____ day of _____, 19____
by _____
(COUNTY OFFICIAL) (DEPUTY)

FILED Jan 4, 1991
BAKER COUNTY SURVEYOR
SURVEY NO. 11-41-6