T. 12 S., R. 41 E., W. M. * Flat File ** Oversize

Filing Date	Section No.	Survey No.	Remarks	Name
February 27, 1963	31	1 *	Map of Survey for J.P. Archuleta	JDH
June 19, 1972	20, 29	2	Baker Co. Road Map - Clarks Creek Rd.	JDH
September 22, 1983	2, 3, 4 & 10	3	Map of Dependent Resurvey	BLM
December 3, 2010	26,27,34,35	3A	MOS - The Record	Benchmark
June 28, 2011	Sec.27,28,29	4	Mineral Valley #2 for 3 Valley Ranch	J.Hambleton
June 28, 2011	R-9	5	CP# 135 "	J.Hambleton
June 28, 2011	R-11	6	CP# 136 "	J.Hambleton
June 28, 2011	R-13	7	CP# 137 "	J.Hambleton
June 28, 2011	R-15	8	CP# 138 "	J.Hambleton
June 28, 2011	T-9	9	CP# 139 "	J.Hambleton
June 28, 2011	T-13	10	CP# 140 "	J.Hambleton
June 28, 2011	T-17	11	CP# 141 "	J.Hambleton
June 28, 2011	V-9	121/4	CP# 142 "	J.Hambleton
June 28, 2011	V-11	13	CP# 143 "	J.Hambleton
June 28, 2011	V-13	14	CP# 144 "	J.Hambleton
June 28, 2011	V-15	15	CP# 145 "	J.Hambleton
June 28, 2011	V-17	16	CP# 146 "	J.Hambleton
August 31, 2011	Sec. 27,28,29	17	MOS Western Mine Development	J.Hambleton
May 3, 2012	A-13	18	Record of Corner Moumentation(11-41-42)	BG&B
May 3, 2012	A-15	19	Record of Corner Moumentation(11-41-43)	BG&B
May 3, 2012	A-17	20	Record of Corner Moumentation(11-41-44)	BG&B
June 12, 2015	Sec. 30 & 31	21	Prop. Line Survey for Dennis Kiely (12-40-14)	J.Hambleton
September 25, 2017	E-1	22	Record of Corner Moumentation(12-40-18)	Butler
September 25, 2017	G-1	23	Record of Corner Moumentation(12-40-20)	Butler
September 25, 2017	J-1	24	Record of Corner Moumentation(12-40-25)	Butler
September 25, 2017	A-1	25	Record of Corner Moumentation(12-41-25)	Butler
September 25, 2017	A-3	26	Corner Restoration	Butler
September 25, 2017	A-5	27	Corner Restoration 11-41-99	Butler
September 25, 2017	A-21	28	Corner Restoration 11-41-100	Butler
September 25, 2017	A-23	29	Corner Restoration	Butler
September 25, 2017	A-25	30	Corner Restoration	Butler
September 25, 2017	C-5	31	Corner Restoration	Butler
September 25, 2017	E-13	32	Corner Restoration	Butler
September 25, 2017	N-5	33	Corner Restoration	Butler
September 25, 2017	N-7	34	Corner Restoration	Butler
September 25, 2017	N-25	35	Corner Restoration 12-40-	Butler
June 17, 2020	SE1/4 SW1/4 of 27	36	MOS of John B. Griffin Placer Claim	J.Swenson
September 24, 2020	NW1/4NE1/4SE1/4of 35	37	MOS of 6 Placer Claims for K & E Excavating Inc.	J.Swenson