

CORNER RESTORATION FORM

Township 14S Range 44E Section 2 County BAKER

State OREGON Date 6/27/2012 Number E-17

Corner Designation : SE COR SEC 2

- Condition Report Only
- Not Found
- Renewed
- Surveyed In
- Referenced

Previous Renewals _____

Monument (s) Found: (Condition and Source)

FOUND 12X12X6 BASALT STONE IN MOUND OF STONES
WITH 5 NOTCHES ON SOUTH FACE AND 1 NOTCHES ON
EAST FACE, IN GOOD CONDITION AS PER ORIGINAL GLO
NOTES.

Accessories Found:

NONE

Monument & Accessories Set (Procedure and Description)

NONE

MONUMENT DETAIL

Found Set

STONE

<p><u>Sketch of Monument, Accessories and General Area</u></p>	<div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">REGISTERED PROFESSIONAL LAND SURVEYOR</p> <p style="text-align: center;"><i>Danny K. Cummings</i></p> <p style="text-align: center;">OREGON JAN. 21, 1988 DANNY K. CUMMINGS 2316</p> </div> <p>RENEWAL DATE : <u>12-31-13</u></p> <p>Agency <u>CK3, LLC</u></p> <p>Party Chief <u>L. KING</u></p> <p>Notekeeper <u>L. KING</u></p> <p>Witness(s) _____</p> <p>Field Book <u>0-269</u></p> <p>Client <u>RISUN TEC.</u></p> <p>Job # <u>V0-12025</u></p> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">COUNTY SURVEYOR RECORDING INFO</p> <p>Received _____</p> <p>Filed _____</p> <p>Survey No. _____</p> <p>Drawing No. _____</p> <p>Index No. _____</p> </div>
--	--

FILED July 29, 2013
 BAKER COUNTY SURVEYOR
 SURVEY NO. 14-44-38